- For the purpose of facility maintenance, we are planning to replace silt fences in front of a screen for Unit 4, for it has been more than 2 years since installation (Starting on September 25).
- Although silt fences in front of screens for Unit 1 and 2 are also older than 2 years old, the frontages are covered with steel pipe sheet piles in accordance with work progress in installing water insulation walls. The height of the tide level changes could be mainly attributed to the south side (Unit 3 side). Therefore, we plan to install a new silt fence between the south seawall of Unit 2 and the water shielding wall steel pipe sheet piles (Starting on September 25).



