


Power Supply to UPS (Uninterruptible Power System)



Upon investigation, it was confirmed that a system trip occurred as a result of UPS failure causing the loss of power supply to the monitoring instrument. The cooling system was recovered by supplying power to the monitoring instrument through a bypass. After replacing the failed UPS, power supply through UPS will be recovered.