

承認	審査	作成
H29.2.10	H29.2.10	H29.2.10

測定場所：北側造成施工エリア（破砕ヤード）


一時保管エリア状況確認 サーベイ記録

件名	伐採木サーベイ（減容前における測定）		
測定日時	平成29年2月10日 9:40 ~ 10:20		
測定者		計測器番号	F1-ICW-081

1 F 構内 全体図



(C)GeoEye / 日本スペースイメージング



A1～A45、B1～B47の測定結果は別紙参照

備考 測定前準備 ■ バッテリーチェック ■ ゼロ点チェック

場所 北側造成施工エリア（破砕ヤード）

別紙

単位： $\mu\text{Sv/h}$

列	No.	線量率	列	No.	線量率	列	No.	線量率	列	No.	線量率
A	1	4.0	A	41	6.5	B	1	11.0	B	41	9.5
A	2	5.0	A	42	5.5	B	2	9.5	B	42	10.0
A	3	6.0	A	43	5.0	B	3	9.0	B	43	12.0
A	4	7.0	A	44	5.0	B	4	8.0	B	44	13.0
A	5	8.0	A	45	4.5	B	5	9.0	B	45	13.0
A	6	5.0				B	6	9.5	B	46	13.0
A	7	4.5				B	7	9.0	B	47	12.0
A	8	4.0				B	8	8.5			
A	9	5.0				B	9	7.0			
A	10	3.5				B	10	7.5			
A	11	3.5				B	11	7.0			
A	12	3.5				B	12	8.0			
A	13	4.0				B	13	7.5			
A	14	3.5				B	14	7.0			
A	15	4.0				B	15	7.0			
A	16	3.5				B	16	7.5			
A	17	4.0				B	17	5.5			
A	18	4.0				B	18	5.5			
A	19	3.5				B	19	6.0			
A	20	3.5				B	20	5.5			
A	21	3.0				B	21	5.5			
A	22	3.5				B	22	6.0			
A	23	4.0				B	23	7.0			
A	24	3.5				B	24	6.5			
A	25	3.5				B	25	6.5			
A	26	4.5				B	26	5.5			
A	27	5.5				B	27	5.0			
A	28	6.5				B	28	4.5			
A	29	7.0				B	29	5.0			
A	30	8.5				B	30	5.5			
A	31	8.0				B	31	5.5			
A	32	14.0				B	32	5.0			
A	33	6.0				B	33	6.0			
A	34	6.0				B	34	5.5			
A	35	5.5				B	35	6.0			
A	36	5.0				B	36	8.0			
A	37	5.5				B	37	8.0			
A	38	6.0				B	38	8.5			
A	39	6.5				B	39	7.0			
A	40	7.0				B	40	7.5			