

# 身体汚染発生状況報告(平成29年5月)

場所:雑固体廃棄物焼却設備建屋

(単位:件数)

| 日  | 身体汚染 | 装備汚染 |
|----|------|------|
| 1  | 0    | 0    |
| 2  | 0    | 0    |
| 3  | 0    | 0    |
| 4  | 0    | 0    |
| 5  | 0    | 0    |
| 6  | 0    | 0    |
| 7  | 0    | 0    |
| 8  | 0    | 0    |
| 9  | 0    | 0    |
| 10 | 0    | 0    |
| 11 | 0    | 0    |
| 12 | 0    | 0    |
| 13 | 0    | 0    |
| 14 | 0    | 0    |
| 15 | 0    | 0    |
| 16 | 0    | 0    |
| 17 | 0    | 0    |
| 18 | 0    | 0    |
| 19 | 0    | 0    |
| 20 | 0    | 0    |
| 21 | 0    | 0    |
| 22 | 0    | 0    |
| 23 | 0    | 0    |
| 24 | 0    | 0    |
| 25 | 0    | 0    |
| 26 | 0    | 0    |
| 27 | 0    | 0    |
| 28 | 0    | 0    |
| 29 | 0    | 0    |
| 30 | 0    | 0    |
| 31 | 0    | 0    |
| 合計 | 0    | 0    |