

# 車両汚染部位記録シート(2019年8月)

(単位:台数)

日	測定台数	13kcpm以上	除染後 退構可車	除染後 退構不可車	除染対象外
1	231	0	0	0	0
2	280	0	0	0	0
3	55	0	0	0	0
4	17	0	0	0	0
5	205	0	0	0	0
6	235	0	0	0	0
7	257	0	0	0	0
8	246	1	0	0	1
9	199	2	1	0	1
10	60	0	0	0	0
11	20	0	0	0	0
12	24	0	0	0	0
13	26	0	0	0	0
14	30	0	0	0	0
15	34	0	0	0	0
16	34	0	0	0	0
17	24	0	0	0	0
18	11	0	0	0	0
19	193	1	1	0	0
20	232	0	0	0	0
21	264	0	0	0	0
22	223	0	0	0	0
23	266	1	1	0	0
24	47	0	0	0	0
25	16	0	0	0	0
26	236	0	0	0	0
27	259	0	0	0	0
28	240	0	0	0	0
29	252	1	1	0	0
30	251	0	0	0	0
31	72	0	0	0	0
合計	4539	6	4	0	2