

身体汚染発生状況報告(2020年9月)

場所: 免震重要棟休憩所 第二工区

(単位: 件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	1	0	0	0
3	1	2	0	0	0
4	0	2	1	0	0
5	0	2	0	0	0
6	0	0	0	0	0
7	0	0	1	0	0
8	0	0	1	0	0
9	0	1	0	0	0
10	1	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	1	0	1	1	0
16	0	0	0	0	0
17	0	0	1	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	1	1	0	0
24	0	0	1	0	0
25	0	0	0	0	0
26	0	1	1	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	1	0	0
合計	3	10	9	1	0

基準値: 4[Bq/cm²]以下

携行品汚染発生状況報告(2020年9月)

場所: 免震重要棟休憩所 第二工区

(単位: 件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	2	0	2	0	2
2	0	0	0	0	0
3	1	0	1	0	1
4	0	0	0	0	0
5	1	0	1	0	1
6	0	0	0	0	0
7	1	0	1	0	1
8	1	0	1	0	1
9	0	0	0	0	0
10	0	1	1	0	1
11	0	0	0	0	0
12	1	0	1	0	1
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	2	0	2	0	2
17	0	0	0	0	0
18	0	0	0	0	0
19	1	0	1	0	1
20	1	1	2	0	2
21	0	0	0	0	0
22	0	0	0	0	0
23	1	0	1	0	1
24	1	0	1	0	1
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	3	0	3	0	3
29	0	0	0	0	0
30	1	0	1	0	1
合計	17	2	19	0	19

身体汚染発生状況報告(2020年9月)

場所: 3/4号機 サービス建屋 休憩所

(単位: 件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
合計	0	0	0	0	0

基準値: 4[Bq/cm²]以下

携行品汚染発生状況報告(2020年9月)

場所: 3/4号機 サービス建屋 休憩所

(単位: 件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
合計	0	0	0	0	0