

身体汚染発生状況報告(2021年2月)

作成日	2021年3月1日(月)
作成者	
審査者	
承認者	

場所:事務本館 汚染検査所

(単位:件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	2	1	0
2	0	1	0	2	0
3	0	1	1	1	0
4	1	0	1	0	0
5	0	0	1	0	0
6	0	0	0	1	0
7	0	0	0	0	0
8	0	0	1	1	0
9	2	0	2	0	0
10	2	1	3	4	0
11	0	0	0	2	0
12	1	0	1	3	0
13	0	0	0	1	0
14	0	0	0	0	0
15	1	1	0	0	0
16	1	1	1	0	0
17	0	0	0	1	0
18	0	0	1	0	0
19	0	0	1	0	0
20	0	0	1	0	0
21	0	0	0	0	0
22	0	0	1	1	0
23	0	0	2	0	0
24	2	1	2	0	0
25	1	0	0	0	0
26	0	1	1	1	0
27	0	0	0	0	0
28	0	0	0	0	0
合計	11	7	22	19	0

基準値:4[Bq/cm²]以下

携行品汚染発生状況報告(2021年2月)

作成日	2021年3月1日(月)
作成者	
審査者	
承認者	

場所:事務本館 汚染検査所

(単位:件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	5	0	5	0	5
2	2	0	2	0	2
3	4	0	4	0	4
4	1	0	1	0	1
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	2	0	2	0	2
9	4	0	4	0	4
10	2	1	3	0	3
11	1	0	1	0	1
12	6	0	6	0	6
13	0	0	0	0	0
14	0	0	0	0	0
15	7	0	7	0	7
16	7	0	7	0	7
17	7	0	7	0	7
18	4	0	4	0	4
19	2	0	2	0	2
20	0	0	0	0	0
21	0	0	0	0	0
22	2	0	2	0	2
23	1	0	1	0	1
24	3	0	3	0	3
25	5	0	5	0	5
26	8	0	8	0	8
27	1	0	1	0	1
28	1	0	1	0	1
合計	75	1	76	0	76

身体汚染発生状況報告(2021年2月)

作成日	2021年3月1日(月)
作成者	
審査者	
承認者	

場所:免震重要棟休憩所 第二工区

(単位:件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	1	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	1	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
合計	0	0	1	1	0

基準値:4[Bq/cm²]以下

携行品汚染発生状況報告(2021年2月)

作成日	2021年3月1日(月)
作成者	
審査者	
承認者	

場所: 免震重要棟休憩所 第二工区

(単位: 件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	1	0	1	0	1
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	1	0	1	0	1
13	0	0	0	0	0
14	1	0	1	0	1
15	0	0	0	0	0
16	2	0	2	0	2
17	0	0	0	0	0
18	1	0	1	0	1
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
合計	6	0	6	0	6

身体汚染発生状況報告(2021年2月)

作成日	2021年3月1日(月)
作成者	
審査者	
承認者	

場所: 3/4号機 サービス建屋 休憩所

(単位: 件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	—	—	—	—	—
2	—	—	—	—	—
3	—	—	—	—	—
4	—	—	—	—	—
5	—	—	—	—	—
6	—	—	—	—	—
7	—	—	—	—	—
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
	0	0	0	0	0
	0	0	0	0	0
	0	0	0	0	0
合計	0	0	0	0	0

基準値: 4[Bq/cm²] 以下

携行品汚染発生状況報告(2021年2月)

作成日	2021年3月1日(月)
作成者	
審査者	
承認者	

場所:3/4号機 サービス建屋 休憩所

(単位:件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	—	—	—	—	—
2	—	—	—	—	—
3	—	—	—	—	—
4	—	—	—	—	—
5	—	—	—	—	—
6	—	—	—	—	—
7	—	—	—	—	—
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
	0	0	0	0	0
	0	0	0	0	0
	0	0	0	0	0
合計	0	0	0	0	0