Fukushima Daiichi Nuclear Power Station Plant Parameters

As of 11:00 on June 10 2023

June 10 2023 TEPCO Holdings Fukushima Daiichi D&D Engineering Company

Status of water injection to the reactor FDW line : 2.4 m²/h FDW line : 1.5 m²/h **6 FDW line : 1.4 m²/h VESSEL BOTTOM HEAD VESSEL BOTTOM HEAD **6 FDW line : 1.4 m²/h **6 CS line : 2.1 m²/h	_
Temperature at the bottom of RPV (TE-263-69G2): 21.2 °C (VESSEL WALL ABOVE BOTTOM HEAD (TE-2-3-69H3): 29.8 °C (TE-2-3-69H1): 25.8 °C (VESSEL BOTTOM ABOVE SKIRT JOT (TE-2-3-69F1): 25.8 °C (TE-2-3-69H1): 25.8 °C (VESSEL WALL ABOVE BOTTOM HEAD (TE-2-3-69F1): 25.8 °C (TE-2-3-69H1): 25.8 °C (TE-2-3-69H	
HVH-12A RETURN AIR RETURN AIR DRYWELL COOLER CTE-1625A) : 21.3 °C (TE-16-114B) : 29.9 °C (TE-16-002) : 23.4 °C CTE-1625F) : 21.2 °C (TE-16-114G#1) : 30.1 °C (TE-16-114F#1) : 24.2 °C (TE-16-114	
Pressure in PCV 0.31 kPa g 2.65 kPa g 0.48 kPa g	_
RPV (RVH-A) : - Nm²/h RPV-A : 6.44 Nm²/h RPV-A : 7.89 Nm²/h RPV-B : 15.01 Nm²/h RPV-B : 6.60 Nm²/h RPV-B : 8.05 Nm²/h RPV	
Outlet flow from PCV gas control system 19.2 m¹/h 16.09 Nm³/h 20.77 Nm³/h	
Hydrogen concentration in PCV ※1 System A : 0.00 vol% System A : 0.01 vol% System A : 0.10 vol% System B : 0.00 vol% System B : 0.06 vol% System B : 0.09 vol%	
System A: Radioactive concentration in PCV (Xe 135) **2 System A: indicated value 1.74E-03 Bq/cm³ detection limit 5.82E-04 Bq/cm³ System A: indicated value ND Bq/cm³ detection limit 1.2E-01 System A: indicated value ND Bq/cm³ System A: indicated value ND Bq/cm³ System B: indicated value ND Bq/cm³ System B: indicated value ND Bq/cm³ System B: indicated value ND Bq/cm³ System A: indicated value ND Bq/cm³ System A: indicated value ND Bq/cm³ System A: indicated value ND Bq/cm³ System B: indicated value ND Bq/cm³ detection limit 1.9E-01 Bq/cm³	
Temperature in the spent fuel pool 28.5 °C 27.6 °C - **5	- *5
FPC skimmer surge tank level 2.73 m 3.89 m - m **7	67.0 ×100mm

[Information about measurements]

※7: Data missing due to work interrupting the measurement.

[Note

Some indicators might not be functioning properly beyond the normal condition for usage affected by the earthquake and subsequent events. We comprehensively evaluate situation in plants using all the available information from indicators and also focusing on trends, taking uncertainty of indicators into consideration.

^{**1 :} In case that the instrument indicates minus hydrogen density, "0%" is recorded (Because there's the possibility of minus indication due to the instrumental precision when hydrogen density is very low.)
The hydrogen concentration in the PCV gas control system is provided.

^{**2 :} In case that the instrument reading is below measurable limit, "ND" is recorded. The radioactivity density (Xe135) in the PCV gas control system is provided.

^{*3:} Flow rate values are adjusted according to the temperature and the pressure under usage conditions.

^{*4:} Nitrogen gas injection is under suspension.

^{%5:} Not monitored as all fuel removal is complete.

^{**6 :} The condensation storage tank reactor water injection systems were switched over to the higher ground reactor water injection systems for the construction to lay pipes. Data sampling by flowmeters of the upland reactor water injection systems.