Fukushima Daiichi Nuclear Power Station Plant Parameters

As of 11:00 on December 15 2023

December 15 2023 TEPCO Holdings Fukushima Daiichi D&D Engineering Company

Status of water FDW line : 2.6 m²/h Silne : 0.0 m²/h Silne : 0.0 m²/h Silne : 1.2 m²/h \$\%6 \) Silne : 0.0 m²/h Silne : 4.1 m²/h \$\%6 \) Silne : 6.1 m²/h Silne : 4.1 m²/h \$\%6 \) Silne : 6.1 m²/h Silne : 6.1 m²/h		Unit 1	Unit 2	Unit 3	Unit 4
Temperature at the bottom of RPV VESSEL ABOVE SKIRT JOINT (TE-263-69H1) : 182 °C RPV TEMPERATURE (TE-23-69H3) : 30.0 °C (TE-2-3-69F1) : 23.8 °C (TE-263-69H1) : 182 °C (TE-263-69H1) : 182 °C (TE-263-69H1) : 182 °C (TE-263-69H1) : 23.9 °C (TE-2-3-69H1) : 23.9 °C (TE-16-20-3-69H2) : 23.9 °C (TE-16-114B1) : 31.7 °C (TE-16-002) : 21.9 °C (TE-16-002) : 21.9 °C (TE-16-114FH1) : 22.9 °C (TE-16	injection to the	· ·	. —	7.0	
Temperature in PCV Temperature in Indicated in Indi	the bottom of	(TE-263-69L1): 20.8 °C VESSEL ABOVE SKIRT JOINT (TE-263-69H1): 18.2 °C VESSEL DOWN COMMER	(TE-2-3-69H3) : 30,0 °C RPV TEMPERATURE	(TE-2-3-69F1) : 23.8 ℃ VESSEL WALL ABOVE BOTTOM HEAD	
Pressure in PCV		(TE-1625A): 20.4 °C HVH-12A SUPPLY AIR	(TE-16-114B) : 31.7 °C SUPPLY AIR D/W COOLER HVH2-16B	(TE-16-002) : 21.9 ℃ SUPPLY AIR D/W COOLER	
Flow rate of nitrosen gas injection to Reactors (JP-A) : 14.78 Nm²/h RPV-B : 6.12 Nm²/h RPV-B : 7.65	Pressure in PCV	0.63 kPa g	2.06 kPa g	0.51 kPa g	_
PCV gas control system Hydrogen concentration in PCV **1 Radioactive concentration in PCV **1 Radioactive concentration in PCV **1 System B: System A: indicated value 1.68E-03 bg/cm² detection limit 5.15E-04 System B: System A: indicated value ND bg/cm² detection limit 1.2E-01 System B:	nitrogen gas injection to Reactors	(RVH-B): 16.02 Nm²/h (JP-A): 14.78 Nm³/h (JP-B): - Nm³/h	RPV-B: 6.12 Nm²/h	RPV-B: 7.65 Nm³/h	
Hydrogen concentration in PCV X1 System A : 0.00 vol% System A : 0.03 vol% System A : 0.13 vol% System B : 0.01 vol% System B : 0.13 vol% System	PCV gas control	1 20.2 111/11	17.99 Nm³/h	21.49 Nm²/h	
indicated value 1.68E-03 Radioactive detection limit 5.15E-04 Radioactive concentration in System B: indicated value ND Bq/cm² detection limit 1.2E-01 indicated value ND Bq/cm² detection limit 1.9E-01 System B: System B:	Hydrogen concentration in	*		-,	
detection limit 3,55E-04 Ba/cm ³ detection limit 1.2E-01 Ba/cm ³ detection limit 1.9E-01	concentration in	indicated value 1.68E-03 detection limit 5.15E-04 System B: indicated value 1.07E-03	indicated value ND Bq/cm² detection limit 1.2E-01 Bq/cm² System B: indicated value ND Bq/cm²	indicated value ND Bq/cm² detection limit 1.9E-01 Bq/cm² System B: indicated value ND Bq/cm²	
Temperature in the spent fuel pool 22.8 °C 22.2 °C - **5 -	the spent fuel	22.8 °C	22.2 °C	- *5	- *5
FPC skimmer surge tank level 4.07 m 4.03 m 3.14 m 43.1 ×100mm		4.07 m	4.03 m	3.14 m	43.1 ×100mm

[Information about measurements]

[Note

Some indicators might not be functioning properly beyond the normal condition for usage affected by the earthquake and subsequent events. We comprehensively evaluate situation in plants using all the available information from indicators and also focusing on trends, taking uncertainty of indicators into consideration.

^{**1 :} In case that the instrument indicates minus hydrogen density, "0%" is recorded. (Because there's the possibility of minus indication due to the instrumental precision when hydrogen density is very low.)

The hydrogen concentration in the PCV gas control system is provided.

^{**2 :} In case that the instrument reading is below measurable limit, "ND" is recorded. The radioactivity density (Xe135) in the PCV gas control system is provided.

^{*3 :} Flow rate values are adjusted according to the temperature and the pressure under usage conditions.

¾4 : Nitrogen gas injection is under suspension.

^{※5 :} Not monitored as all fuel removal is complete.

 ^{#6 :} Data missing due to work interrupting the measurement.