Fukushima Daiichi Nuclear Power Station Plant Parameters

As of 11:00 on March 25 2025

March 25 2025 TEPCO Holdings Fukushima Daiichi D&D Engineering Company

	Unit 1	Unit 2	Unit 3	Unit 4
Otatus of Water	·	FDW line: 0.0 m³/h CS line: 1.3 m³/h	FDW line: - m¹/h	
Temperature at the bottom of	ESSEL ABOVE SKIRT JOINT	VESSEL WALL ABOVE BOTTOM HEAD (TE-2-3-69H3): 23.2 °C RPV TEMPERATURE (TE-2-3-69R): 25.1 °C	VESSEL BOTTOM ABOVE SKIRT JOT (TE-2-3-69F1): 17.6 °C VESSEL WALL ABOVE BOTTOM HEAD (TE-2-3-69H1): 16.1 °C	
Temperature in PCV	(TE-1625A) : 18.1 °C	RETURN AIR DRYWELL COOLER (TE-16-114B): 23.5 °C SUPPLY AIR D/W COOLER HVH2-16B (TE-16-114G#1): 23.7 °C	PCV Temperature (TE-16-002): 15.0 °C SUPPLY AIR D/W COOLER (TE-16-114F#1): 15.7 °C	
Pressure in PCV 0.	0.05 kPag	1.86 kPa g	0.52 kPa g	_
Flow rate of nitrogen gas injection to Reactors	(JP-A) : 14.35 Nm³/h	RPV-A: 6.02 Nm²/h RPV-B: 6.02 Nm²/h PCV: - Nm²/h **4	RPV-A: 6.65 Nm²/h RPV-B: 6.56 Nm²/h PCV: 8.53 Nm²/h	
Outlet flow from PCV gas control system	20.0 m³/h	16.97 Nm³/h	23.83 Nm²/h	
	*	System A : 0.06 vol% System B : 0.06 vol%	System A: 0.50 vol% System B: 0.49 vol%	
Radioactive	indicated value 1.87E-03 Bq/cm³ 4.91E-04	System A: indicated value ND detection limit 1.2E-01 System B: indicated value ND detection limit 1.2E-01 ND Bq/cm³ Bq/cm³	System A: indicated value detection limit System B: indicated value detection limit ND Bq/cm² Bq/cm² ND Bq/cm² ND Bq/cm²	
Temperature in the spent fuel pool	38.5 ℃	19.8 °C	- *5	- **5
	- m	6.67 m *9	- m	31.4 ×100mm

Some indicators might not be functioning properly beyond the normal condition for usage affected by the earthquake and subsequent events. We comprehensively evaluate situation in plants using all the available information from indicators and also focusing on trends, taking uncertainty of indicators into consideration.

[[]Information about measurements]

#1: In case that the instrument indicates minus hydrogen density, "0%" is recorded. Because there's the possibility of minus indication due to the instrumental precision when hydrogen density is very low.)

The hydrogen concentration in the PCV gas control system is provided.

#2: In case that the instrument reading is below measurable limit. "ND" is recorded. The radioactivity density 0xe135) in the PCV gas control system is provided.

#3: Flow rate values are adjusted according to the temperature and the pressure under usage conditions.

^{**4 :} Nitrogen gas injection is under suspension.**5 : Not monitored as all fuel removal is complete.

^{*}K6 : The primary coolant pump in the Unit 1 spent fuel pool is now suspended.
*7 : Predicted temperature of the spent fuel pool water due to suspension of the primary pump for the Unit 1 spent fuel pool cooling system. **R : The reducted temperature of the spent float pool water due to suspens and on the primary pound for the Onlin't spent float pool would represent the proposition of the primary pound float or the primary confidence of the primary coolant pump in the Unit 2 spent float pool is now suspended.
 **Ho : The primary coolant pump in the Unit 2 spent float pool is now suspended.
 **10 : Data missing due to work interrupting the measurement.