

<Marine Organism Rearing Log>

9 AM, August 25, 2022

Weather: Sunny

Water temperature: 17.7°C

Equipment installation status of rearing test (within controlled area) ②

In the rearing test, the equipment used in the rearing training is used as the basis, the layout is devised in consideration of handling ALPS treated water.

Moreover, we are taking measures to prevent ALPS treated water to leak outside of the facility by setting up weirs on each tanks.

