
Detailed Analysis Results in the Port of Fukushima Daiichi NPS, around Discharge Channel and Bank Protection (Pumped Water Obtained from Bank Protection)

Unit: Bq/L

ped water from ter observation hole
No.0-3-2
ec 19, 2013
12:00 PM
ND(0.44)
ND(0.51)
ND(20)
69,000

^{*} Data announced this time is provided in a thick-frame. The other data was announced on December 20.

* "-" indicates that the measurement was out of range.



^{* &}quot;ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.