Sampling Results Regarding the Influence on the Water Leak at a Tank in the H4 area in Fukushima Daiichi Nuclear Power Station (Around the H4 Area)

 	D . //
 ınıt.	Bq/L
 'I II L.	DU/L

	Groundwater around H4 area								
	E-1	E-2	E-3	E-4	E-5	E-6	E-7	E-8	
Date of Sampling	Oct 11, 2013	Oct 11, 2013	Oct 11, 2013	Oct 11, 2013	Oct 11, 2013				
Time of sampling	9:07 AM	9:16 AM	9:27 AM	9:38 AM	9:55 AM				
ΑΙΙ β	140	89	83	36	40				
H-3 (Approx. 12 years)	300,000	370	210	310	2,400				

