Sampling Results Regarding the Influence on the Water Leak at a Tank in the H4 area in Fukushima Daiichi Nuclear Power Station (Pump Well)

Unit: Bq/L

| | Pump wells of the groundwater bypass | | | | | |
|------------------|--------------------------------------|--------------|--------------|--------------|--------------|--------------|
| | No.7 | No.8 | No.9 | No.10 | No.11 | No.12 |
| Date of Sampling | Sep 10, 2013 | Sep 10, 2013 | Sep 10, 2013 | Sep 10, 2013 | Sep 10, 2013 | Sep 10, 2013 |
| Time of sampling | 9:40 AM | 9:45 AM | 9:50 AM | 9:55 AM | 9:00 AM | 9:10 AM |
| ΑΙΙ β | ND(15) | ND(15) | ND(15) | ND(15) | ND(15) | ND(15) |
| Tritium | 440 | 60 | 44 | 230 | 280 | 760 |

^{* &}quot;ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.