# Definite Results of Nuclides Analysis at Fukushima Daiichi Nuclear Power Station (Announced on October 16 - 31, 2013)

< Legend > ー: γ nuclides except for the major 3 nuclides (I-131, Cs-134, Cs-137) were not detected. ⇒ Please refer to the preliminary reports for the result of the major nuclides.
〇: γ nuclides other than the major 3 nuclides (I-131, Cs-134, Cs-137) were detected. ⇒ Please refer to the following pages.
／: Not applicable or cancelled due to the bad weather.

| Announcement Date of the Preliminary Report / Sampling Point | October | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 |
| Nuclides Analysis Result of the Radioactive Materials in the Air at Fukushima Nuclear Power Stations | – | – | – | – | – | – | – | – | – | – | – | – | – | – | – | – |
| Nuclides Analysis Result of the Radioactive Materials in the Air at the Sea Side of Fukushima Nuclear Power Stations | ／ | ／ | – | ／ | ／ | ／ | ／ | ／ | ／ | – | ／ | ／ | ／ | ／ | ／ | ／ |
| Nuclides Analysis Result of Radioactive Materials in the Seawater < Coast > | – | ／ | – | – | – | – | – | – | – | – | – | – | – | – | – | – |
| Nuclides Analysis Result of the Radioactive Materials in the Seawater of the Port | – | ／ | – | – | – | – | – | – | – | – | – | – | – | – | – | – |
| Nuclides Analysis Result of the Sub-drain of Fukushima Daiichi NPS | ／ | – | ／ | – | ／ | ／ | – | ／ | – | ／ | – | ／ | ／ | – | ／ | – |
| Nuclides Analysis Result of the Marine Soil | ／ | ／ | – | ／ | ／ | ／ | ／ | ／ | ／ | – | ／ | ／ | ／ | ／ | ／ | ／ |
| Nuclides Analysis Result of the Sub-drain Water in the Surroundings of the Central Radioactive Waste Treatment Facility | – | – | – | – | – | – | – | – | – | – | – | – | – | – | – | – |
| Nuclide Analysis of the Radioactive Materials in the Fallouts obtained inside and outside of Fukushima Daiichi Nuclear Power Station | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | – | ／ |
| Nuclides Analysis Results of the Radioactive Materials in the Air at the Opening of Buildings at Fukushima Daiichi NPS | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | – | ／ |
| Nuclides Analysis Result of the Radioactive Materials in the Air at the Upper Part of Unit 1 Reactor Building | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | ／ | – | ／ |