Sampling Results Regarding the Water Leak at the Tanks in the H4 area and the B area in Fukushima Daiichi Nuclear Power Station (South Water Outlet, Drainage Channel)

Unit: Bq/L

	Seawater of the		Side ditch next to the tank (X-2)	Side ditch next to the tank (point immediately short of the junction with the drainage channel C) (X-1)	drainage channel C and the side ditch	Sampling points of the inside of drainage channel B					
		Junction of the drainage channels B and C Note 2 (C-1)				high dose equivalent	Downstream of B-1 (B-2)	Point immediately short of the junction with the drainage channel C (B-3)	Intersection in the	date in the drainage	Drainage channel C
Date of Sampling	Oct 19, 2013	Oct 19, 2013	Oct 19, 2013	Oct 19, 2013	Oct 19, 2013	Oct 19, 2013	Oct 19, 2013	Oct 19, 2013	Oct 19, 2013	Oct 19, 2013	Oct 19, 2013
Time of sampling	10:35 AM	11:52 AM	10:55 AM	11:00 AM	11:09 AM	* Note 4	* Note 4	11:55 AM Note 4	11:35 AM	11:42 AM	10:50 AM
Cs-134(Approx. 2 years)	ND(1.1)	ND(18)	42	98	ND(18)	* Note 4	* Note 4	100 Note 4	ND(20)	ND(19)	ND(19)
Cs-137(Approx.30 years)	1.7	ND(26)	88	230	ND(27)	* Note 4	* Note 4	260 Note 4	ND(26)	ND(26)	ND(26)
ΑΙΙ β	ND(21)	83	800	1,600	110	* Note 4	* Note 4	12,000 Note 4	ND(14)	ND(14)	150

Note 1: Approx. 330m south from Unit 1-4 water outlet (T-2)

Note 2: Same sampling point as side ditch in front of the core warehouse sampled on August 19 (announced on August 20) and August 20 (announced on August 21)

- Note 3: Water inflow location of drainage channel to the tank area
- Note 4: Collection of accumulated water and cleaning of the ditch are ongoing.

^{* &}quot;ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

