

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (6.7E-01)	ND (5.6E-01)	Treated water tank	Jun 26, 2014	4:00 PM
Cs-137	ND (6.3E-01)	ND (7.3E-01)			
Gross β	ND (4.7E+00)	ND (4.5E+00)			
Tritium	1.9E+02	1.6E+02	Receiving tank	Jun 25, 2014	10:00 AM
Notification density rate*	0.18	0.17			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.