

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (6.3E-01)	ND (7.6E-01)	Treated water tank	Aug 1, 2014	3:00 PM
Cs-137	ND (6.3E-01)	ND (9.9E-01)			
Gross β	ND (3.7E+00)	ND (4.4E+00)			
Tritium	6.3E+02	6.4E+02	Receiving tank	Jul 30, 2014	10:00 AM
Notification density rate*	0.15	0.18			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.