

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (6.4E-01)	ND (6.9E-01)	Treated water tank	Aug 11, 2014	4:00 PM
Cs-137	ND (4.6E-01)	ND (8.7E-01)			
Gross β	ND (8.0E-01)	ND (8.9E-01)			
Tritium	2.5E+02	2.3E+02	Receiving tank	Aug 7, 2014	12:40 PM
Notification density rate*	0.047	0.055			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.