

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (7.1E-01)	ND (7.2E-01)	Treated water tank	Aug 20, 2014	3:35 PM
Cs-137	ND (6.8E-01)	ND (7.0E-01)			
Gross β	ND (4.5E+00)	ND (4.1E+00)			
Tritium	2.5E+02	2.4E+02	Receiving tank	Aug 18, 2014	1:00 PM
Notification density rate*	0.17	0.16			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.