

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (8.3E-01)	ND (7.0E-01)	Treated water tank	Aug 22, 2014	4:30 PM
Cs-137	ND (7.1E-01)	ND (8.7E-01)			
Gross β	ND (4.1E+00)	ND (4.3E+00)			
Tritium	8.7E+02	8.1E+02	Receiving tank	Aug 20, 2014	11:10 AM
Notification density rate*	0.17	0.18			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.