

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (6.0E-01)	ND (6.9E-01)	Treated water tank	Aug 26, 2014	4:30 PM
Cs-137	ND (5.8E-01)	ND (8.1E-01)			
Gross β	ND (9.4E-01)	ND (8.6E-01)			
Tritium	2.8E+02	2.8E+02	Receiving tank	Aug 22, 2014	12:30 PM
Notification density rate*	0.052	0.054			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.