

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (5.9E-01)	ND (6.8E-01)	Treated water tank	Sep 4, 2014	4:00 PM
Cs-137	ND (5.3E-01)	ND (7.4E-01)			
Gross β	ND (9.0E-01)	ND (9.7E-01)			
Tritium	2.2E+02	1.9E+02	Receiving tank	Sep 2, 2014	3:01 PM
Notification density rate*	0.049	0.055			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.