

## Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

### <Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND ( 6.5E-01 )	ND ( 7.2E-01 )	Treated water tank	Sep 8, 2014	3:50 PM
Cs-137	ND ( 5.3E-01 )	ND ( 7.6E-01 )			
Gross β	ND ( 3.7E+00 )	ND ( 4.6E+00 )			
Tritium	1.2E+02	1.2E+02	Receiving tank	Sep 5, 2014	2:50 PM
Notification density rate*	0.14	0.18			

\* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

\* Analysis of tritium is performed at Environment Management Building.