

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (6.8E-01)	/	Treated water tank	Sep 27, 2014	3:10 PM
Cs-137	ND (5.8E-01)				
Gross β	ND (4.4E+00)				
Tritium	8.9E+02		Receiving tank	Sep 25, 2014	1:20 PM
Notification density rate*	0.18				

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.