

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (5.5E-01)	/	Treated water tank	Oct 11, 2014	2:00 PM
Cs-137	ND (5.8E-01)				
Gross β	ND (3.9E+00)				
Tritium	8.3E+02		Receiving tank	Oct 9, 2014	1:30 PM
Notification density rate*	0.16				

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.