

## Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

### <Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND ( 6.5E-01 )	ND ( 6.4E-01 )	Treated water tank	Oct 22, 2014	4:50 PM
Cs-137	ND ( 5.8E-01 )	ND ( 8.8E-01 )			
Gross β	ND ( 7.8E-01 )	ND ( 7.8E-01 )			
Tritium	4.2E+02	ND ( 3.5E+02 )	Receiving tank	Oct 20, 2014	10:30 AM
Notification density rate*	0.050	0.052			

\* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

\* Analysis of tritium is performed at Environment Management Building.