

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (6.2E-01)		Treated water tank	Nov 15, 2014	3:40 PM
Cs-137	ND (6.5E-01)				
Gross β	ND (3.7E+00)				
Tritium	2.6E+02		Receiving tank	Nov 13, 2014	12:20 PM
Notification density rate*	0.15				

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.