				Unit: Bq/L
	Seawater of the south water outlet Note 1 (near the drainage channel exit) (T-2)	Drainage channel C OP.35 exit (C-2)	Point near the main gate in the drainage channel C Note 2 (C-0)	Point near Fureai Intersection in the drainage channel B Note 2 (B-0-1)
Date of Sampling	May 15, 2014	May 15, 2014		May 15, 2014
Time of sampling	7:45 AM	7:37 AM		7:27 AM
Cs-134(Approx. 2 years)	ND(1.1)	ND(18)		ND(16)
Cs-137(Approx.30 years)	ND(1.7)	ND(26)		ND(24)

ND(14)

		Unit: Bq/L
	Side ditch next to the tank (point immediately short of the junction with the drainage channel C) (X-1)	Side ditch next to the tank (X-2)
Date of Sampling	May 15, 2014	May 15, 2014
Time of sampling	7:47 AM	7:48 AM
Cs-134(Approx. 2 years)	ND(17)	ND(18)
Cs-137(Approx.30 years)	36	ND(26)
Gross β	55	66

Drainage channel C

B south area

Gross β

Note 2: Water inflow location of drainage channel to the tank area

ND(18)

<Reference> The Highest Dose Until the Previous Measurement

Unit: Bq/L

	Seawater of the south water outlet Note 1 (near the drainage channel exit) (T-2)	Drainage channel C OP.35	Point near the main gate in the drainage channel C Note 2 (C-0)
Cs-134(Approx. 2 years)	3.5 (11/9)	45 [9/26]	20 <2/15>
Cs-137(Approx.30 years)	8.1 [9/15,11/9]	130 [9/26]	51 <2/15>
Gross β	ND	2,500 [10/24]	120 <2/15>

Linit: Ba/L

			Uliit. Bq/L
	Point near Fureai Intersection in the drainage channel B Note 2 (B-0-1)	Side ditch next to the tank (point immediately short of the junction with the drainage channel C) (X-1)	Side ditch next to the tank (X-2)
Cs-134(Approx. 2 years)	110 <5/1>	450 [10/4]	260 [11/10]
Cs-137(Approx.30 years)	280 <5/1>	990 [10/4]	530 [11/10]
Gross β	380 (9/2)	15,000 [10/2]	15,000 [10/14]

^{*} Sampling date is provided in parentheses. []: 2013, <>: 2014

25

* The ducting is provided in the dot line.

Drainage channel B

Point near Fureai Intersection in the drainage channel B

H4 north area

Tank area

Point near the main gate in the drainage channel C

Seawater of the south water (near the drainage channel

exit) C-2

Drainage channel C O.P.35

Point immediately short of the junction with the drainage channel C

Side ditch next to the tank

* There is no outflow from the sampling point X-1 and X-2 to the drainage channel C, since they are

completely isolated from the drainage channel C.

Note 1: Approx. 330m south from Unit 1-4 water outlet (T-2)

^{* &}quot;ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.