

Nuclides Analysis Result of the Sub-drain Water in the Surroundings of the Central Radioactive Waste Treatment Facility

I-131(Bq/cm³)

Sampling Location	Nov 30	Dec 01	Dec 02	Dec 03	Dec 04	Dec 05	Dec 06	Dec 07	Dec 08	Dec 09	Dec 10	Dec 11	Dec 12	Dec 13	Dec 14	Dec 15	Dec 16	Dec 17	Dec 18			
①	ND	*1																				
②	ND	ND	*1																			
③	ND	ND	*1																			
④	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
⑤	ND	ND	*1																			
⑥	-	ND	-	-	-	-	-	-	ND	-	-	-	-	-	-	ND	-	-	-	-		
⑦	ND	ND	*1																			
⑧	ND	ND	*1																			
⑨	ND	ND	*1																			

Cs-134(Bq/cm³)

Sampling Location	Nov 30	Dec 01	Dec 02	Dec 03	Dec 04	Dec 05	Dec 06	Dec 07	Dec 08	Dec 09	Dec 10	Dec 11	Dec 12	Dec 13	Dec 14	Dec 15	Dec 16	Dec 17	Dec 18			
①	ND	ND	*1																			
②	ND	ND	*1																			
③	ND	ND	*1																			
④	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
⑤	ND	ND	*1																			
⑥	-	ND	-	-	-	-	-	-	ND	-	-	-	-	-	-	ND	-	-	-	-		
⑦	0.017	0.015	0.023	0.018	0.013	0.038	0.013	ND	0.027	0.011	0.027	0.024	0.026	0.021	0.034	0.02	0.03	0.014	*1			
⑧	ND	ND	ND	0.015	ND	ND	ND	ND	0.012	0.015	ND	0.01	ND	ND	ND	ND	ND	0.016	*1			
⑨	ND	*1																				

Cs-137(Bq/cm³)

Sampling Location	Nov 30	Dec 01	Dec 02	Dec 03	Dec 04	Dec 05	Dec 06	Dec 07	Dec 08	Dec 09	Dec 10	Dec 11	Dec 12	Dec 13	Dec 14	Dec 15	Dec 16	Dec 17	Dec 18			
①	ND	ND	*1																			
②	ND	ND	*1																			
③	ND	ND	*1																			
④	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
⑤	ND	ND	*1																			
⑥	-	ND	-	-	-	-	-	-	ND	-	-	-	-	-	-	ND	-	-	-	-		
⑦	0.055	0.052	0.11	0.046	0.054	0.081	0.046	0.037	0.045	0.04	0.09	0.086	0.072	0.058	0.081	0.097	0.086	0.067	*1			
⑧	0.028	0.035	0.04	0.041	ND	0.019	0.02	0.022	0.049	0.03	0.023	0.031	0.024	0.035	0.025	0.022	ND	0.023	*1			
⑨	ND	*1																				

* Hyphen "-" indicates that neither sampling nor measurement was implemented.

* ⑥ was selected as a sampling location in the upstream of groundwater (sampling done once a week starting from April 29, 2011) since it became unable to do sampling at ④.

* Sampling at ⑦ (located in the downstream of the groundwater) has been done since May 26, 2011.

* Sampling at ⑧ since May 30, 2011

* Sampling at ⑨ has been done since August 2, 2011

* "ND" indicates that the measurement result is below the detection limit. Dec 18,2014 Not sampled because of bad weather

<Place of Sampling>

- ① Southeast of Unit 4 Turbine Building
- ② Northeast of the Process Main Building
- ③ Southeast of the Process Main Building
- ④ Southwest of the Process Main Building
- ⑤ South Part of the Miscellaneous Solid Waste Volume Reduction Treatment Building
- ⑥ Southwest Part of the On-site Bunker Building
- ⑦ West Side of the Incineration Workshop Building
- ⑧ North Part of the Miscellaneous Solid Waste Volume Reduction Treatment Building
- ⑨ Southeast Part of the On-site Bunker Building