



The seawall area at Fukushima Daiichi NPS

<Reference>
November 27, 2013
Tokyo Electric Power Company

Movement in groundwater (Between Unit 1 and 2: From Oct. 26 to Nov. 26)




Progress in the ground improvement work between Unit 1 and 2 (As of in the morning on Nov. 27)




東京電力

*Chemical injection was implemented NOT in this range, but in the range of green color. We would like to correct it and apologize for the misinformation. (Revised on December 12, 2013)


Movement in groundwater (Between Unit 2 and 3: From Oct. 26 to Nov. 26)



Progress in the ground improvement work between Unit 2 and 3 (As of in the morning on Nov. 27)




Movement in groundwater (Between Unit 3 and 4: From Oct. 26 to Nov. 26)



Progress in the ground improvement work between Unit 3 and 4 (As of in the morning on Nov. 27)

Ground improvement (sea side):
up to 30 out of 132
(Since Aug. 23, 2013)

Ground improvement (mountain side):
up to 36 out of 273
(Since Oct. 19, 2013)



* The work area is subject to change due to the on-site situation.