# <Draining Water on Underground Floor of Turbine Building (T/B)>

Status of highly concentrated accumulated radioactive water treatment facility and storage tank facility [Treatment Facility]

- ·6/17 20:00 Full operation of radioactive material removal instruments started.
- ·6/24 12:00 Start of desalination facilities operation
- ·6/27 16:20 Circulating injection cooling started.
- ·8/7 16:11 Evaporative Concentration Facility has started full operation.
- •8/19 19:33 We activated 2nd cesium adsorption facility (System B) and started the treatment of accumulated water by the parallel operation of cesium adsorption instrument and decontamination instrument. At 19:41, the flow rate achieved a steady state.

### [Storage Facility]

·6/8 ~ Large tanks to store and keep treated or contaminated water have been transferred and installed sequentially.

Accumulated water in vertical shafts of trenches and at basement level of building

| Unit   | Draining water source Place transferred   | Status                               |
|--------|---|--------------------------------------|
| Unit 1 | ·Unit 1T/B Unit 2T/B  | ·14:00 on December 10 - Transferring |
| Unit 2 | ·Unit 2T/B Central Radioactive Waste Treatment Facility [Miscellaneous Solid Waste Volume Reduction Treatment Building (High Temperature Incinerator Building)] | ·18:03 on November 30 - Transferring |
| Unit 3 | · Unit 3T/B Central Radioactive Waste Treatment Facility [Process Main Building]  | ·9:25 on November 15 -12/5 10:31     |
| Unit 6 | ·Unit 6T/B Temporary tanks  | December 11 No transfer planned.     |

| Place transferred   | Status of Water Level (As of December 11 at 7:00)  |  |  |  |  |
|---|--|--|--|--|--|
| Process Main Building   | Water level: O.P.+ 1,825 mm(Accumulated total increase: 3,042 mm)  |  |  |  |  |
| 1 Tocess Main Building  | 104 mm decrease since 7:00 on December 10  |  |  |  |  |
| Miscellaneous Solid Waste<br>Volume Reduction Treatment<br>Building<br>(High Temperature Incinerator<br>Building) | Water level: O.P.+ 1,108 mm(Accumulated total increase: 1,834 mm) 50 mm decrease since 7:00 on December 10 |  |  |  |  |

## Water level of the vertical shaft of the trench, T/B and R/B(As of December 11 at 7:00)

|        | Vertical Shaft of Trench      | T/B  | R/B  |
|--------|-------------------------------|--|--|
| Unit 1 | O.P. <+ 850 mm                | O.P.+ 3,458 mm   | O.P.+ 3,906 mm   |
|        | (No change since 7:00 on      | (239 mm decrease since 7:00 on                                   | (19 mm decrease since 7:00 on                                    |
|        | December 10 )                 | December 10 )  | December 10 )  |
| Unit 2 | O.P.+ 2,800 mm                | O.P.+ 2,821 mm   | O.P.+ 2,947 mm   |
|        | (9 mm increase since 7:00 on  | (7 mm increase since 7:00 on                                     | (3 mm increase since 7:00 on                                     |
|        | December 10)                  | December 10)   | December 10 )  |
| Unit 3 | O.P.+ 3,285 mm                | O.P.+ 3,052 mm   | O.P.+ 3,280 mm   |
|        | (16 mm increase since 7:00 on | (17 mm increase since 7:00 on                                    | (20 mm increase since 7:00 on                                    |
|        | December 10 )                 | December 10 )  | December 10 )  |
| Unit 4 | -                             | O.P.+ 3,040 mm<br>(22 mm increase since 7:00 on<br>December 10 ) | O.P.+ 3,052 mm<br>(15 mm increase since 7:00 on<br>December 10 ) |

# <Monitoring of Radioactive Materials>

Nuclide Analysis of Seawater (Reference)

| Place of sampling                                   | Date of  | Time of  | Ratio of density limit (times) |        |        |
|---|----------|----------|--------------------------------|--------|--------|
| Flace of Sampling                                   | sampling | sampling | I-131                          | Cs-134 | Cs-137 |
| Approx. 30m North of Discharge Channel of 5,6U, 1F  | 12/10    | 8:45     | ND                             | 0.06   | 0.05   |
| Approx. 330m South of Discharge Channel of 1-4U, 1F | 12/10    | 8:20     | ND                             | 0.03   | 0.03   |
| Around 3,4u Discharge Channel of 2F                 | 12/10    | 8:00     | ND                             | 0.02   | 0.02   |
| Approx. 7km South of 1,2U Discharge Channel of 2F   | 12/10    | 7:35     | ND                             | ND     | 0.01   |

### <Cooling of Spent Fuel Pools > (As of December 11 at 11:00)

| Unit   | Cooling type               | Status of cooling | Temperature of water in<br>Pool |  |
|--------|----------------------------|-------------------|---------------------------------|--|
| Unit 1 | Circulating Cooling System | Under operation   | 13.5                            |  |
| Unit 2 | Circulating Cooling System | Under operation   | 28.9                            |  |
| Unit 3 | Circulating Cooling System | Under operation   | 14.4                            |  |
| Unit 4 | Circulating Cooling System | Under operation   | 21                              |  |

[Unit 2] ·12/10 11:37 We restarted the alternative cooling system for the spent fuel pool.

[Unit 4] ·11/29 ~ We started operation of the ion exchange equipment to remove salt from spent fuel pool.

### < Water Injection to Pressure Containment Vessels > (As of December 11 at 11:00)

| Unit   | Status of injecting water   | Feed-water<br>nozzle<br>temp. | Reactor pressure vessel bottom temp. | Pressure of primary containment vessel |
|--------|---|-------------------------------|--------------------------------------|--|
| Unit 1 | Injecting freshwater<br>(Feed Water System: Approx. 4.2m <sup>3</sup> /h,<br>Core Spray System: Approx. 2.0 m <sup>3</sup> /h)  | 42.6                          | 43.5                                 | 110.2 kPaabs                           |
| Unit 2 | Injecting freshwater (Feed Water System: Approx. 2.9m³/h, Core Spray System: Approx. 6.0 m³/h)                                  | 69.5                          | 74.5                                 | 111 kPaabs                             |
| Unit 3 | Injecting freshwater<br>(Feed Water System: Approx. 3.0 m <sup>3</sup> /h,<br>Core Spray System: Approx. 6 0 m <sup>3</sup> /h) | 58.6                          | 65.6                                 | 101.6 kPaabs                           |

[Unit 1] · 12/10 10:09 Regarding water injection to the reactor, we started injection from the Core Spray System in addition to the Feed Water System.

10:11 We adjusted water injection from Core Spray System to approx. 1.0 m³/h. (Water injection from the Feed Water System continued with the level of approx. 4.2 m³/h)

·12/11 10:30 We adjusted water injection from Core Spray System from approx. 1.0 m³/h to approx. 2.0 m³/h. (Water injection from the Feed Water System continued with the level of approx. 4.2 m³/h).

[Unit 2] ·12/10 11:25 Regarding water injection to the reactor, we adjusted water from the Core Spray System from approx. 4.5m³/h to approx. 5.5m³/h. (Water injection Feed Water System continued with the level of approx. 2.9 m³/h.)

·12/11 10:44 We adjusted water injection from Core Spray System from approx. 5.6 m³/h to approx. 6.0 m³/h, while we adjusted water injection from the Feed Water System from approx. 2.5 m³/h to approx. 3.0 m³/h

[Unit 3] ·12/10 11:25 We have adjusted water injection from the Feed Water System from approx. 2.2m³/h to approx. 3.2 m³/h.

(Water injection from the Core Spray System continued with the level of approx. 6.0 m<sup>3</sup>/h)

·12/11 11:10 Because we found that there was small vibration at the Flow Control Valve of Core Spray System, we adjusted water injection from Core Spray System from approx. 6.1 m³/h to approx. 6.5 m³/h, while we adjusted water injection from the Feed Water System from approx. 3.1 m³/h to approx. 2.5 m³/h. Because the vibration of the Flow Control Valve still

continued, we adjusted water injection from the Feed Water System to approx. 3.0 m³/h, and from Core Spray System to approx. 6.0 m³/h. Because the vibration is tiny and would do little influence on pipe arrangements and others, we will study on its countermeasure later.

[Unit 4] [Unit 5] [Unit 6] No major change

#### <Others>

·10/7 ~ Continuously implementing water spray using water after purifying accumulated water of Unit 5 and Unit 6 to prevent spontaneous fire of trimmed trees and diffusion of dust.