

**Status of Water Leakage on the 1st floor of Unit 4 Reactor Building, Fukushima
Daiichi Nuclear Power Station
(Test line of the Piping for Jet Pump Measurement)**



Rack for Jet Pump Measurement



Closed Valve
Close-up of the Leakage Point
Leakage Point