


Ocean soil covering work in front of the intake channel of Fukushima Daiichi Nuclear Power Station

Situation of the field test construction and covering condition


<Reference>
March 13, 2012
Tokyo Electric Power Company



Situation of the field test construction in front of the intake channel of Unit 1-4
February 28, 2012



Sea floor condition before covering
February 6, 2012



Sea floor condition after 1st layer covering
February 29, 2012



Sea floor condition after 2nd layer covering
March 10, 2012