



Countermeasures against Water Leakage from Condensed Water Transportation Line of Water Desalinations (Reverse Osmis Membrane)

March 28, 2012
Tokyo Electric Power Company



<H6 area (left) and H4 area (right)>



<H6 area (east side)>



<H6 area (west side)>

Shooting Date: March 27, 2012 (upperleft), March 28, 2012 (right)
Photo by: Tokyo Electric Power Company (All 3 photos)