## Work Schedule of the Main Inspection/Restoration of the Kashiwazaki-Kariwa Nuclear Power Station in Response to the Niigata-Chuetsu-Oki Earthquake(during 4 Weeks)(1/1)

【Inspection/Restoration Status】
◆From January 8, 2012 (Sun) to February 4, 2012 (Sat)

	System / Equipment	Items	January 8 (Sun) to January 14 (Sat)	January 15 (Sun) to January 21 (Sat)	January 22 (Sun) to January 28 (Sat)	January 29 (Sun) to February 4 (Sat)	Status of Inspection / Restoration	
Unit 2	Turbine facilities	Turbine inspection					High-pressure turbine and low-pressure turbine (A) (B) (C) detailed inspection commenced on Dec. 7, 2009.	
						High-pressure turbine and low-pressure turbine (A) (B) (C) restoration work commenced on		
							Dec. 12, 2011.	
	Other facilities	Main generator inspection					Inspection commenced on Mar. 19, 2008.	
	Seismic reinforcement	Seismic reinforcement works such as pipe supports		1			Reinforcement work commenced on Feb. 1, 2011.	
Unit 3	Reactor facilities	Primary containment vessel closure					Closure work commenced on Mar. 3, 2011.	
	Verification of system integrity	System functional test					System functional test commenced on Nov. 16, 2010.	
Unit 4	Turbine facilities	Turbine inspection					High-pressure turbine and low-pressure turbine (A) (B) (C) detailed inspection commenced	
						on Aug. 3, 2009. High-pressure turbine and low-pressure turbine (A) (B) (C) restoration work commenced on		
							Jul. 5, 2010.	
	Other facilities	Main generator inspection				Inspection commenced on Jan. 15, 2008.		
		ection of power supply input transformer of the primary						
	loop recirculation system adjustable speed drive					Carrying in and installation work commenced on Jun. 12, 2009.		
	G-it	Seismic reinforcement works such as pipe supports					Reinforcement work commenced on Jan. 17, 2011. Reinforcement work for attached structure of reactor pressure vessel commenced on Jun. 27, 2011.	
	Seismic reinforcement				1	1		

<sup>\*</sup> Inspection results for each facilities will be announced as soon as they compiled.

<sup>\*</sup> Inspection and restoration work and execution date for each item may alter according to the situation.

<sup>\*</sup> Unit 5 and Unit 6 are in operation, and Unit 1 and Unit 7 are in periodical inspection.